

REP KIT	FP801S	5A	
	FP802S	2A	
	ICS801CS	SQD2011K	
	QP801CS	60R360P	
	PC801	817B	
	PC802	817B	
	PC803	817B	
	ICP801	S3050	8er
	ICM801	3110A	8er
	RP813	30 Ohm	
	RP810	10 Ohm	
	DP801	BAV70	
	DP804	BAV70	
	DP803	?	

Fehlercode 2 RS802 (10R)

FP801S	5A	
DS806	1N4007	
DS804	1N4007	
DS803	1N4007	
FP802S	2A	
ICS801S	SQD2011K	8er
DP808C	BYV29X600 FMN-1106	
DP805	1N5408	
DP803	1N5408	
QP801CS	13NM60 60R360	
DS853C	SR5100	
DM861C	SR5100	
DM862C	SR5100	
DM863C	SR5100	
DM864C	SR5100	
DM851C	SF26G	
DM853C	SF26G	
DM855C	SF26G	
DM857C	SF26G	
QM802CS	14NM50 6R380	
QM801CS	14NM50 6R380	
QM854	AOD4186	
Q9101C	AOD9N40	
Q9102C	AOD9N40	
ICP801S	SEM3050	8er
ICM801S	SEM3110A	8er
IC9801	7014X	8er
IC9802	7014X	8er